





Assembly instruction Series N / C 0000179851




Old instruction No. 03063


Tools and materials required : Stanley blade Scissors Crimp tool (see table below)	straight connectors for flexible cabel				
	Cabel entry : SUHNER Full-Crimp				
	Connector types : (e.g.)				
	25 N-50-3-6 24 N-50-3-11 21 N-50-3-7 11 C-50-3-7	25 N-50-3-7 25 N-50-3-25 24 N-50-3-12 24 N-50-3-16 21 N-50-3-8 11 N-50-3-33 11 C-50-3-8	21 N-75-4-8 11 N-75-4-8	21 N-75-4-9 11 N-75-4-9	
This connector is supplied in 3 parts.	suitable cables e.g. :	RG 58C/U	RG 223/U	RG 59B/U	G 04233 D
	Centre contact :	cavity 2	cavity 2	cavity 2	cavity 2
	Braid :	cavity B	cavity B	cavity C	cavity C
	Crimp tool :	2 B (orange)	2 B (orange)	2 C (yellow)	2 C (yellow)




Slide ferrule A onto cabel.
Prepare cabel according to diagram.
CAUTION: Do not damage braid, dielectric and inner conductor of cable!



Push contact B over inner conductor to abut cable dielectric and crimp.



Splay out braid and insert cable in connector body C until contact B engages perceptibly. Ensure that braid lies above the crimp neck.



Slide ferrule A over braid and crimp as close to connector body C as possible.





The cable assembly of R.F. connectors can only be done by well trained assembly staff and suitable assembly equipment. Huber+Suhr's skilled staff and specialised equipment are available to carry out complete R.F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.

Revision	B
Date	18.06.2015
Initiator	4726/Bom


Deutscher Text: siehe Rückseite




Benötigte Hilfsmittel : Stanley-Messer Schere Klemmwerkzeug (siehe Tabelle)	Gerade Verbinder für flexible Kabel				
	Kabeleinführung : SUHNER Voll-Klemmung				
Dieser Verbinder wird in 3 losen Teilen geliefert.	Verbinder-Typen : (z.B.)				
		25 N-50-3-7			
		25 N-50-3-25			
		24 N-50-3-12			
		24 N-50-3-16			
	25 N-50-3-6	24 N-50-3-11	21 N-50-3-8	21 N-75-4-8	21 N-75-4-9
	24 N-50-3-11	21 N-50-3-8	11 N-50-3-33	11 N-75-4-8	11 N-75-4-9
	21 N-50-3-7	11 N-50-3-33	11 C-50-3-8		
	11 C-50-3-7	11 C-50-3-8			
Geeignete Kabel :	RG 58C/U	RG 223/U	RG 59B/U	G 04233 D	
Innenleiter :	Aussparung 2	Aussparung 2	Aussparung 2	Aussparung 2	
Aussenleiter :	Aussparung B	Aussparung B	Aussparung C	Aussparung C	
Klemmwerkzeug :	2 B (orange)	2 B (orange)	2 C (gelb)	2 C (gelb)	




Hülse A auf das Kabel schieben.
Kabel gemäss Figur abisolieren.
ACHTUNG: Abschirmung, Dielektrikum und Innenleiter nicht beschädigen!



Kontakt B über Kabelinnenleiter bis zum Dielektrikum stossen und klemmen.



Abschirmung leicht aufspreizen und Kabel in Gehäuse C einführen bis der Kontakt B fühlbar einrastet.
Abschirmung muss über dem Klemmhals liegen.



Hülse A über Abschirmung schieben und möglichst nahe am Gehäuse C klemmen.

Die Montage von HF-Verbindern kann nur durch geschultes Personal, das über die richtige Ausrüstung verfügt, erfolgen. Huber+Suhr verfügt über ausgebildete Fachkräfte und rationelle Einrichtungen zur Herstellung kompletter HF-Verbindungsleitungen. Wir montieren Ihre Verbinder zu wirtschaftlichen Preisen! Wenden Sie sich an unsere Vertreter.

Version	B
Datum	18.06.2015
Erstellt	4726/Bom